

BOX SOFIE - MONTAGE HANDLEIDING

A = 1x

B = 1x

C = 1x

D = 1x

E = 1x

F = 4x

1K

H =	49B M6*50 x16
J =	6A x1
K =	40D 5mm x4
L =	36A M6*25 x4
M =	4 x4
N =	5 M6 x4

